

pCon.planner-Shortcuts

Content

1	Application menu	2
2	General	
3	Start	2
4	Edit	3
5	Articles	4
6	Presentation	4
7	View	
	7.1 Render	4
	7.2 Projection	4
	7.3 Camera	5
	7.4 Viewports	5
8	Navigate	5
9	Select objects	6
10	During the planning process	6
11	Media Browser	7
12	Folder Manager [pCon.planner PRO]	8



1 Application menu

Create a new drawing	Ctrl + N
Open drawing	Ctrl + O
Save the current drawing	Ctrl + S
Save the current drawing with a new name	Shift + Ctrl + S
Start/Terminate Layout mode [pCon.planner PRO]	F7
Print preview	Shift + Ctrl + P
Edit document settings	Alt + Enter
Configure program settings	F11
Terminate pCon.planner	Alt + F4

2 General

Open pCon.planner Help Center	F1
Show or hide ribbon	Shift + Ctrl + F1
Activate Commando Box	Alt+M

3 Start

Paste	Ctrl + V Insert
Cut	Ctrl + X
Сору	Ctrl + C Ctrl + Insert
Delete	Ctrl + D Delete
Copy Image	Ctrl + J
Open OFML product catalog [pCon.planner PRO/ME]	F6
Open pCon.catalog	F3
Open Trimble 3d Warehouse	F8



Hide Selection	Ctrl + T
Hide Others	Ctrl + K
Show All	Ctrl + R

4 Edit

Ungroup selected groupCtrl + ULock selected objectsCtrl + Shift + HUnlock locked objectsCtrl + Shift + VRotate toolCtrl + Shift + VRotate toolCtrl + Shift + RScale toolCtrl + Shift + LQuick CopyCtrl + QLine up toolCtrl + Shift + UArrangementShift + Ctrl + ARegion toolCtrl + Shift + ERegion toolCtrl + Shift + GExtrude toolCtrl + Shift + KMirror toolCtrl + Shift + CInsert Point toolCtrl + Shift + C2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference (pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + HFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + TShow Property EditorF12	Create group from selected objects	Ctrl + G
Unlock locked objectsCtrl + Shift + HMove toolCtrl + Shift + VRotate toolCtrl + Shift + RScale toolCtrl + Shift + RQuick CopyCtrl + QLine up toolCtrl + Shift + UArrangementShift + Ctrl + AReplaceCtrl + Shift + GExtrude toolCtrl + Shift + GExtrude toolCtrl + Shift + MHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + 1Follow Me tool [pCon.planner PRO/STD]Ctrl + Shift + T	Ungroup selected group	Ctrl + U
Move toolCtrl + Shift + VRotate toolCtrl + Shift + RScale toolCtrl + Shift + RQuick CopyCtrl + QLine up toolCtrl + Shift + UArrangementShift + Ctrl + AReplaceCtrl + Shift + ERegion toolCtrl + Shift + GExtrude toolCtrl + Shift + KMirror toolCtrl + Shift + CHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + TTape Measure toolCtrl + Shift + T	Lock selected objects	Ctrl + H
Rotate toolCtrl + Shift + RScale toolCtrl + Shift + LQuick CopyCtrl + QLine up toolCtrl + Shift + UArrangementShift + Ctrl + AReplaceCtrl + Shift + ERegion toolCtrl + Shift + GExtrude toolCtrl + Shift + AMirror toolCtrl + Shift + MHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + FIsolate reference copiesCtrl + Shift + NTape Measure toolCtrl + Shift + WTape Measure toolCtrl + Shift + T	Unlock locked objects	Ctrl + Shift + H
Scale toolCtrl + Shift + LQuick CopyCtrl + QLine up toolCtrl + Shift + UArrangementShift + Ctrl + AReplaceCtrl + Shift + ERegion toolCtrl + Shift + GExtrude toolCtrl + Shift + XMirror toolCtrl + Shift + NHatch [pCon.planner PRO/STD]Ctrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + T	Move tool	Ctrl + Shift + V
Quick CopyCtrl + QLine up toolCtrl + Shift + UArrangementShift + Ctrl + AReplaceCtrl + Shift + ERegion toolCtrl + Shift + GExtrude toolCtrl + Shift + GExtrude toolCtrl + Shift + NMirror toolCtrl + Shift + CInsert Point toolCtrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + 1Follow Me tool [pCon.planner PRO/STD]Ctrl + Shift + 1Follow Me tool [pCon.planner PRO/STD]Ctrl + Shift + T	Rotate tool	Ctrl + Shift + R
Line up toolCtrl + Shift + UArrangementShift + Ctrl + AReplaceCtrl + Shift + ERegion toolCtrl + Shift + GExtrude toolCtrl + Shift + GExtrude toolCtrl + Shift + XMirror toolCtrl + Shift + MHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + 1Follow Me tool [pCon.planner PRO/STD]Ctrl + Shift + 1Follow Me tool [pCon.planner PRO/STD]Ctrl + Shift + T	Scale tool	Ctrl + Shift + L
ArrangementShift + Ctrl + AReplaceCtrl + Shift + ERegion toolCtrl + Shift + GExtrude toolCtrl + Shift + GMirror toolCtrl + Shift + XMirror toolCtrl + Shift + MHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + ITape Measure toolCtrl + Shift + T	Quick Copy	Ctrl + Q
ReplaceCtrl + Shift + ERegion toolCtrl + Shift + GExtrude toolCtrl + Shift + GExtrude toolCtrl + Shift + XMirror toolCtrl + Shift + MHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + ITape Measure toolCtrl + Shift + T	Line up tool	Ctrl + Shift + U
Region toolCtrl + Shift + GExtrude toolCtrl + Shift + XMirror toolCtrl + Shift + MHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + ITape Measure toolCtrl + Shift + T	Arrangement	Shift + Ctrl + A
Extrude toolCtrl + Shift + XMirror toolCtrl + Shift + MHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + 2Isolate reference copiesCtrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + ITape Measure toolCtrl + Shift + T	Replace	Ctrl + Shift + E
Mirror toolCtrl + Shift + MHatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + WTape Measure toolCtrl + Shift + T	Region tool	Ctrl + Shift + G
Hatch [pCon.planner PRO/STD]Ctrl + Shift + CInsert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + ITape Measure toolCtrl + Shift + T	Extrude tool	Ctrl + Shift + X
Insert Point toolCtrl + Shift + N2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + WTape Measure toolCtrl + Shift + T	Mirror tool	Ctrl + Shift + M
2D Symbol [pCon.planner PRO/STD]Ctrl + Shift + 2Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + WTape Measure toolCtrl + Shift + T	Hatch [pCon.planner PRO/STD]	Ctrl + Shift + C
Reference [pCon.planner PRO/STD]Ctrl + Shift + FIsolate reference copiesCtrl + Shift + IFollow Me tool [pCon.planner PRO/STD]Ctrl + Shift + WTape Measure toolCtrl + Shift + T	Insert Point tool	Ctrl + Shift + N
Isolate reference copies Ctrl + Shift + I Follow Me tool [pCon.planner PRO/STD] Ctrl + Shift + W Tape Measure tool Ctrl + Shift + T	2D Symbol [pCon.planner PRO/STD]	Ctrl + Shift + 2
Follow Me tool [pCon.planner PRO/STD] Ctrl + Shift + W Tape Measure tool Ctrl + Shift + T	Reference [pCon.planner PRO/STD]	Ctrl + Shift + F
Tape Measure tool Ctrl + Shift + T	Isolate reference copies	Ctrl + Shift + I
	Follow Me tool [pCon.planner PRO/STD]	Ctrl + Shift + W
Show Property Editor F12	Tape Measure tool	Ctrl + Shift + T
	Show Property Editor	F12



Show Layer dialog	F4	

5 Articles

Article List [pCon.planner PRO/ME]	Ctrl + E
Copy Article List [pCon.planner PRO/ME]	Ctrl + B

6 Presentation

Layout [pCon.planner PRO]	F7
Print preview	Shift + Ctrl + P

7 View

7.1 Render

Show the drawing in wireframe representation	Shift + F1
Show the drawing in hidden line representation	Shift + F2
Show the drawing in colored representation	Shift + F3
Show the drawing in textured representation	Shift + F4
Show the drawing in shaded representation	Shift + F6
Show the drawing in realistic representation	Shift + F7

7.2 Projection

Show the drawing from orthographic view	Ctrl + 1
Show the drawing in the perspective view	Ctrl + 3
Show the drawing from top	Ctrl + 4
Show the drawing from front	Ctrl + 5
Show the drawing from right side	Ctrl + 6



Show the drawing from left side	Ctrl + 7
Show the drawing from bottom-up	Ctrl + Shift + 4
Show the rear of the drawing	Ctrl + Shift + 5
Show the drawing from north east direction	Ctrl + Shift + 6
Show the drawing from north west direction	Ctrl + Shift + 7
Show the drawing from south east direction	Ctrl + Shift + 8
Show the drawing from south west direction	Ctrl + Shift + 9

7.3 Camera

Zoom into view	Ctrl + +
Zoom out of view	Ctrl + -
Zoom view to extents	Ctrl + Space
Zoom view to selection extents	Shift + Space
Zoom all viewports to extents	Shift + Ctrl + Space

7.4 Viewports

Switch to single viewport	Ctrl + F1
Split screen horizontally into two viewports	Ctrl + F2
Split screen vertically into two viewports	Ctrl + F3
Split screen into four viewports	Ctrl + F4
Split screen into one big and one small view	Ctrl + F5
Split screen into one big and three small viewports	Ctrl + F6
Enter/Leave full screen mode	F5

8 Navigate

Allows moving downwards in projection Perspective	F	
Allows moving upwards in projection Perspective	R	



Pressing Shift while using the PAN changes the layer on which the panning is performed in the projection Perspective	Shift
Moving forward in the projection Perspective	W
Moving leftward in the projection Perspective	А
Moving backwards in the projection Perspective	S
Moving rightward in the projection Perspective	D
Rotating upwards in projection Perspective	Cursor up
Rotating downwards in projection Perspective	Cursor down
Rotating left in projection Perspective	Cursor left
Rotating right in projection Perspective	Cursor right
Navigation through obstacles	Shift + Zoom
Quit current navigation mode	Esc

9 Select objects

Allows to select multiple objects	Ctrl
Select all objects in the drawing	Ctrl + A
Invert current selection	Ctrl + I
Unselect current selection	Esc
Select parent element in open article	Ctrl + M Shift + Mouse Left

10 During the planning process

Pressing the Alt key while drawing a wall switches the end point of the wall	Alt
Pressing the Alt key while moving an object creates a reference of the selected object	Alt
Pressing the Crtl key while moving an object creates a copy of the selected object	Ctrl
Switch the wall orientation while drawing a wall	Ctrl



Move the reference point (UCS)	Space
Change position of reference point between origin of WCS, the user's last selected UCS position and pCon.planner's last suggestion	С
Rotate reference point (UCS) or set direction of the World Coordinate System (WCS)	V
Repeat the last operation	F2
Cancel current work step	Esc
Undo the last operation	Ctrl + Z
Redo the last undo operation	Shift + Ctrl + Z
While applying tools like rotate or scale the Tab key allows to switch between the shown values	Tab
Lock/Unlock axis	Shift
Enable/Disable Axis Snap (for example while moving an object)	G
Enable/Disable Object Snap (for example while moving an object)	Н
Pressing the Shift key while inserting an article from the Catalog will keep the article close but open a Configuration after insertion	Shift
Take the strength of a wall and use it for the wall that is currently being drawn [pCon.planner PRO/STD]	Т
Wall Dimension for length of complete wall only	Shift + Click
Replace objects	Shift + Ctrl + E
Direct Insertion of Articles and Geometry	Alt [+ Shift + [Ctrl]]
Right of current selection	Alt
Left of current selection	Shift + Alt
Above current selection	Ctrl + Alt
Before current selection	Ctrl + Shift + Alt

11 Media Browser

Select all entries Ctrl + A	
Delete selected entries Delete	

12 Folder Manager [pCon.planner PRO]

Create new folder	F7
Delete selected folders	Delete
Rename selected folder	F2
Move selected articles to other side	F6
Mark all	Ctrl + A
Move selected articles upwards (chance position of article)	Ctrl + Up
Move selected articles downwards (change position of article)	Ctrl + Down



Legal remarks

© EasternGraphics GmbH | Albert-Einstein-Straße 1 | 98693 Ilmenau | GERMANY

This work (whether as text, file, book or in other form) is copyright. All rights are reserved by EasternGraphics GmbH. Translation, reproduction or distribution of the whole or parts thereof is permitted only with the prior agreement in writing of EasternGraphics GmbH.

EasternGraphics GmbH accepts no liability for the completeness, freedom from errors, topicality or continuity of this work or for its suitability to the intended purposes of the user. All liability except in the case of malicious intent, gross negligence or harm to life and limb is excluded.



All names or descriptions contained in this work may be the trademarks of the relevant copyright owner and as such legally protected. The fact that such trademarks appear in this work entitles no-one to assume that they are for the free use of all and sundry.